



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

| Lakewood Elementary School | | | | | | | |
|----------------------------|---|-------------------|----------------|------------------------------|---------------------|---------------------|--|
| Date of Sampling: 10/27/18 | | | | | | | |
| Sampler: Amanda Peterson | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes |
| Lakewood-01 | Teacher's Lounge Across Main Office, Faucet | KF | 4:13 PM | 5 | ND ³ | Y | First Draw |
| Lakewood-02 | Hallway, Outside Main Office, Bottle Fill, Water Cooler | BT | 4:05 PM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. |
| Lakewood-03 | Room 103, Faucet | F | 4:15 PM | 5 | ND | Y | First Draw. Drains Slow. |
| Lakewood-04 | Room 109, Faucet | C | 4:46 PM | 5 | 2 | N | First Draw |
| Lakewood-06 | Hallway, Outside of Gym, Left Bubbler | B | 5:00 PM | 5 | ND | N | First Draw. Corrosion Noted at Bubbler. |
| Lakewood-07 | Room 108, Faucet | C | 4:48 PM | 5 | ND | Y | First Draw. Corrosion Noted at Faucet. |
| Lakewood-08 | Room 108, Bubbler | C | 4:50 PM | 5 | ND | N | First Draw |
| Lakewood-09 | Hallway, Outside Main Office, Bottle Fill | BT | 4:06 PM | 5 | ND | N | First Draw |
| Lakewood-10 | Hallway, Outside of Kitchen, Bottle Fill, Water Cooler | BT | 3:30 PM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. |
| Lakewood-11 | Kitchen, 3-Compartment, Faucet | KF | 3:35 PM | 5 | ND | Y | First Draw |
| Lakewood-12 | Room A-5, Bubbler | C | 3:43 PM | 5 | ND | N | First Draw. Corrosion Noted at Bubbler. |
| Lakewood-13 | Room A-5, Faucet | C | 3:44 PM | 5 | ND | N | First Draw. Drains Slow. |
| Lakewood-14 | Room A-6, Bubbler | C | 3:40 PM | 5 | 1 | N | First Draw |
| Lakewood-15 | Room A-6, Faucet | C | 3:41 PM | 5 | ND | N | First Draw |
| Lakewood-16 | Room A-4, Bubbler | C | 3:49 PM | 5 | ND | N | First Draw. Corrosion Noted at Bubbler. |

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

| Lakewood Elementary School | | | | | | | |
|----------------------------|--|-------------------|----------------|------------------------------|---------------------|---------------------|--|
| Date of Sampling: 10/27/18 | | | | | | | |
| Sampler: Amanda Peterson | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes |
| Lakewood-17 | Room A-4, Faucet | C | 3:50 PM | 5 | 2 | N | First Draw |
| Lakewood-18 | Room A-3, Bubblers | C | 3:53 PM | 5 | ND | N | First Draw |
| Lakewood-19 | Room A-3, Faucet | C | 3:53 PM | 5 | 1 | N | First Draw |
| Lakewood-21 | Room A-2, Faucet | C | 3:57 PM | 5 | ND | Y | First Draw |
| Lakewood-22 | Room A-1, Bubblers | C | 3:59 PM | 5 | 4 | N | First Draw. Corrosion Noted at Bubblers. |
| Lakewood-23 | Room A-1, Faucet | C | 4:01 PM | 5 | 1 | N | First Draw |
| Lakewood-24 | Outside Room A-6, Faucet | F | 3:39 PM | 5 | 3 | Y | First Draw |
| Lakewood-25 | Outside Room A-1, Faucet | F | 3:55 PM | 5 | 1 | Y | First Draw. Drains Slow. |
| Lakewood-26 | Hallway, Outside of Kitchen, Bottle Fill | BT | 3:31 PM | 5 | ND | N | First Draw |
| Lakewood-27 | Cafeteria, Bubblers | B | 3:37 PM | 5 | 3 | N | First Draw. Corrosion Noted at Bubblers. |
| Lakewood-28 | Clinic, Bubblers | C | 4:07 PM | 5 | ND | N | First Draw. Corrosion Noted at Bubblers. |
| Lakewood-29 | Clinic, Faucet | C | 4:08 PM | 5 | ND | Y | First Draw |
| Lakewood-30 | Outside Room D-6, Faucet | F | 4:17 PM | 5 | ND | Y | First Draw |
| Lakewood-31 | Room 106, Bubblers | C | 4:42 PM | 5 | ND | N | First Draw |
| Lakewood-32 | Room 106, Faucet | C | 4:44 PM | 5 | ND | Y | First Draw |
| Lakewood-33 | Room 107, Bubblers | C | 4:52 PM | 5 | 1 | N | First Draw. Corrosion Noted at Bubblers. Low Flow. |
| Lakewood-34 | Room 107, Faucet | C | 4:56 PM | 5 | 2 | N | First Draw |
| Lakewood-35 | Hallway, Outside of Gym, Right Bubblers | B | 4:48 PM | 5 | ND | N | First Draw. Corrosion Noted at Bubblers. |

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

| Lakewood Elementary School | | | | | | | |
|----------------------------|--------------------------|-------------------|----------------|------------------------------|---------------------|---------------------|--|
| Date of Sampling: 10/27/18 | | | | | | | |
| Sampler: Amanda Peterson | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes |
| Lakewood-36 | Room D-4, Bubblers | C | 4:23 PM | 5 | ND | N | First Draw. Discoloration Noted Around Bubblers. |
| Lakewood-37 | Room D-4, Faucet | C | 4:22 PM | 5 | 2 | Y | First Draw |
| Lakewood-38 | Room D-5, Bubblers | C | 4:21 PM | 5 | 1 | N | First Draw |
| Lakewood-39 | Room D-5, Faucet | C | 4:20 PM | 5 | ND | Y | First Draw |
| Lakewood-40 | Room D-6, Bubblers | C | 4:18 PM | 5 | ND | N | First Draw. Low Flow. |
| Lakewood-41 | Room D-6, Faucet | C | 4:19 PM | 5 | 7 | Y | First Draw |
| Lakewood-42 | Room D-1, Bubblers | C | 4:25 PM | 5 | ND | N | First Draw |
| Lakewood-43 | Room D-1, Faucet | C | 4:24 PM | 5 | ND | Y | First Draw |
| Lakewood-44 | Room D-2, Bubblers | C | 4:25 PM | 5 | ND | N | First Draw. Low Flow. |
| Lakewood-45 | Room D-2, Faucet | C | 4:26 PM | 5 | 2 | Y | First Draw |
| Lakewood-46 | Room D-3, Bubblers | C | 4:28 PM | 5 | ND | N | First Draw |
| Lakewood-47 | Room D-3, Faucet | C | 4:29 PM | 5 | ND | Y | First Draw |
| Lakewood-48 | Outside Room D-1, Faucet | F | 4:30 PM | 5 | 1 | Y | First Draw |

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb